

RECENT HEAT STRAIGHTENING REPAIR JOBS

HSE Job Number	Owner	GC	Year Performed	Job Name	Description
F-5210170	High Associates	High Associates	2021	Building 225 Column Straightening	Straightening of building column that was hit by forklift
Before			After		
					
F-5200077	NYS DOT	Bette & Cring	2020	TANY 20-3B Brookside Rd Steel Repair	Removed portion of girder, then straightened ends due to extreme damage
Before			After		
					
F-5190141	PADOT	HRI	2019	Centre Co Heat Straightening	Straightened girder then added cover plates to reinforce
Before			After		
					